

SDMS DocID

476282

FIELD INVESTIGATIONS OF UNCONTROLLED HAZARDOUS WASTE SITES

FIT PROJECT

TDD # F1-8005-01F

December 5, 1980

TASK REPORT TO THE ENVIRONMENTAL PROTECTION AGENCY CONTRACT NO. 68-01-6056

Superfund Records Center SITE: Olin BREAK: 13

SITE INSPECTION REPORT of OLIN CHEMICALS GROUP PLANT

Eames Street Wilmington, Massachusetts

Submitted to:
John Hackler, Chief
Office of Uncontrolled Waste Sites
U.S. EPA, Region I

Submitted by:
David Cook, Project Leader
Ecology and Environment, Inc. (E & E)
FIT Team, Region I

ecology and environment, inc.

International Specialists in the Environmental Sciences

SITE INSPECTION REPORT

FOR

OLIN CHEMICAL GROUP WILMINGTON PLANT

TDD #:

F1-8005-01F

Firm Name:

Olin Chemicals Group

Address:

Eames Street

Wilmington, Massachusetts

Telephone:

203-356-3156

Owner:

Corporation

Principal Contact at Site:

Mr. David Vaughn

(Hartford Office)

1. Purpose of Inspection:

To gather information and samples necessary to determine the potential for possible RCRA and/or 311/104 Clean Water Act actions against Olin Chemical Group.

2. Objective:

To conduct an on-site investigation of the Wilmington Plant site in order to locate evidence of contamination, identify possible contaminants and collect appropriate samples for screening and analysis.

3. Background:

3.1 Description:

The Olin Chemicals Group Wilmington Plant occupies a 53-acre site south of Eames Street in Wilmington, Massachusetts. The site is bounded on the east by the Boston and Maine railroad tracks, on the south by the Woburn-Wilmington town line, on the west by a Boston and Maine railroad spur, and on the north by Eames Street (See Figures 1 and 2). The property was purchased by Olin Chemicals Group in September, 1980 from the Stepan Chemical Company which had occupied the site since 1971. Chemical plant operations on this site began in 1953 under the ownership of National Polychemicals, Inc. which merged with Stepan Chemical Company in 1971. The northern one-half of the site is occupied by the production facilities, and the southern one-half is wooded. A drainage ditch parallel to the Boston and Maine tracks borders the eastern project site boundary and carries water from north to south. This drainage ditch continues adjacent to the tracks until its confluence with Hall's Brook about 0.9 miles south of the site. Nearly all surface water on the site is routed to a single channel which flows into the drainage ditch, as shown in Figure 2.




Figure 1 - Location Map of Olin Chemicals Group Wilmington Plant.

3.1 Description -continued

At the time when the aerial photograph presented in Figure 3 was taken (April 24, 1971), three acid pits existed to the south of the processing facilities. These pits have been replaced by rectangular settling basins as shown in Figure 4 (photographed on April 29, 1977). An extensive area of distressed vegetation is present in the east-central portion of the property. Also on the property are eleven large storage tanks noted in Figure 4. there are twelve wells on the property as noted in Figure 2.

3.2 Primary Site Activity:

Several chemicals have been synthesized on-site from a variety of ingredients. The processes used and the final products are as follows (quantities based on 1973 production figures):

Opex Process - Dinitropentamethylenetetramine (DNPT), a slightly water soluble solid used as a blowing agent in the production of expanded rubber compounds, 1.2 million pounds per year.

Kempore Process - Azodicarbonamide (Kempore), also a slightly water soluble solid used as a rubber blowing agent, 1.6 to 1.8 million pounds per year.

Wytox Process - Wytox, a liquid phosphite rubber stabilizer, one million pounds per year.

Wytox ADP-X Process - Dioctyldiphenylamine (DODPA), a dark colored resinous solid, 600,000 pounds per year.

O.B.S.H. Process - Oxybisbenzenesulfonylhydrazide (OBSH), a rubber blowing agent, 300,000 pounds per year.





Figure 3 - April 24, 1971

Aerial Photograph Showing the Location of the Former Acid Pits.




3.2 Primary Site Activity - continued

Raw materials and waste products for the preceding processes are listed in Table 1. Only those waste products discharged into the yard or floor drainage system are listed. The drainage system is shown in Figure 5.

In addition to the above processes, numerous coatings for rubber products were produced on site. The following chemicals were used to produce the coatings:

Bentone
Santocel
Ufamite MM 67
Toluene
Butylacetate
Acrylic Resins
Maleic Anhydride
Glycerine
Fatty Amines
Silicone
Monoethanolamine
Mineral Oil



3.2 Primary Site Activity - continued

TABLE 1 - Raw Materials and Waste Products Associated With Chemical Processes Used by National Polychemicals, Inc. and Stepan Chemical Company between 1953 and 1978.

Process	Raw Materials	Waste Products
0pex	anhydrous ammonia formaldehyde sodium nitrite hydrochloric acid	sodium chloride formaldehyde sodium nitrite process oil
Kempore	liquid chlorine urea sodium hydroxide sulfuric acid hydrazine	sodium sulfate sodium chloride ammonium sulfate urea sulfuric acid
Wytox	phosphorous trichloride paraformaldehyde nonyl phenol	None sewered
Wytox ADP-X	diphenylamine diisobutylene aluminum chloride	diisobutylene aluminum hydroxide sodium chloride
0.B.S.H.	diphenyloxide chlorosulfonic acid	sulfuric acid

3.2 Primary Site Activity - continued

According to MDC records, the following materials were being stored on-site as of June 30, 1980:

MAT	TERIAL BEING STORED:	Annual Thruput (gals.)	Type of Storage Container (tank, drum, etc.)	
1.	Formaldehyde	172,500	Tank	13,300
2.	Nonyl phenol	281,600	Tank	10,000
3.	Dinonyl phenol	30,500	Tank	6,700
4.	Ethyl hexoic acid	18,400	Tank	5,000
5.	Dioctylphthlate	54,200	Tank	15,000
6.	Process 0il	11,800	Tank	4,250
7.	TNPP (Wytox 312)	50,000	Tank	10,000

Chemicals used or manufactured at this site are transported in 55-gallon drums by railcar.

3.3 Secondary site activity:

Not applicable

3.4 Hazards Identified or Alleged:

Potential sources of contamination as a result of on-site activities past or present are the following:

- 1. Leaking of materials from storage tanks.
- 2. Leaching of materials from acid pits.
- 3. Leaching of materials from burial sites.
- 4. Exfiltration from sewers.

A close examination of the chemicals which have been used on-site indicates that only a small number may have contributed or are contributing to an environmental hazard. Toluene and dioctylphthalate are included in the Federal Register list of priority pollutants. It is highly likely that toluene would have volatilized soon after a spill. Dioctylphthalate is very persistent and has been associated with pneumonia-like symptoms. Several other chemicals used on site including hydrazine, nonylphenol, dinonylphenol, and ethyl hexoic acid may cause undesirable symptoms. The extensive vegetative stress noted on-site is probably the result of high sodium chloride and sulfuric acid concentrations leaching from the former acid pits.

Prior to 1971, all waste materials were disposed of on-site either into a series of three acid pits or directly into a series of channels on the property. Eventually, all material either leached or drained into the ditch paralleling the Boston and Maine railroad tracks and proceeded ultimately to the Aberjona River. In 1971, disposal of wastes was changed to the system presently in use. Sulfate bearing wastes are mixed with a calcium hydroxide slurry to form a calcium sulfate sludge which is disposed of in two polyvinyl chloride (PVC)-lined lagoons. An analysis of this sludge is as follows (analyzed by National Polychemicals, Inc., September 1970):

3.4 Hazards Identified or Alleged - continued

Water	27,500 lbs.	
Gypsum	26,800 lbs.	
CaCO ₃	650 lbs.	
Calcium Oxbisbenzene	Sulfonate Trace	
Na ₂ SO ₄	Trace	
A1 (OH) ₃	Trace	
NaC1	Trace	
CaC1 ₂	Trace	
Formaldehyde	Trace	
NaNO ₂	Trace	
NH ₄ C1	Trace	

TOTAL 54,950 lbs. = 27.5 Tons/Day

A study performed in 1979 by Geotechnical Engineers, Inc. of Winchester, Massachusetts, indicated that several holes exist in the PVC liner (See Figures 6 to 8). It was also discovered that sludge has been dumped in an emergency lagoon when the two existing lagoons filled to capacity (See Figure 4). This emergency lagoon had no liner and was formed by dredging soil to form a roughly rectangular area. Solids from the lagoons are dredged periodically and landfilled on the southwest corner of the property. The landfill site was approved by the State Department of Environmental Quality Engineering (DEQE). The analysis of the sludge indicates that no environmental hazards would result from leaching of the lagooned or landfilled materials into the ground.

Non-sulfate bearing wastes generated on-site are presently discharged into an underground sewer line which connects to a Town of Wilmington owned sewer. This line connects to a Metropolitan District Commission (MDC) sewer line. Complaints regarding high chloride, sulfate and ammonia levels in the sewer effluent have been made on several occasions.




Figure 6 - Leak Along the Seam of the Polyvinyl Chloride Liner in the Sulfate Sludge Lagoon.




Figure 7 - Enlargement from Figure 6.



<u>Figure 8</u> - Hole in the Polyvinyl Chloride Liner Associated with the Sulfate Sludge Lagoon.

3.4 Hazards Identified or Alleged - continued

An unofficial report from a former Stepan employee indicates that phosphorus trichloride was often dumped directly into the ground and that residues were buried next to the wetlands near the drainage channel. Sediment and ground water samples were taken in an attempt to confirm or deny the existence of an environmental hazard resulting from such alleged activities.

A 1977 aerial photograph shows two areas where drums were stored on-site (See Figure 4). Leaks in these drums may have resulted in ground water contamination. The 1971 photo (Figure 3) also reveals a spill generating from the group of six large storage tanks on the east side of the property. Since 1973, "black ooze" has been noted seeping into the drainage ditch paralleling the railroad tracks east of the site (Figure 9). A sample was taken by the E & E. FIT team on October 2, 1980, (See memo to John Hackler from David Cook dated October 6, 1980). A conversation between D. Cook (E & E) and D. Vaughn (Olin) revealed that dioctylphthalate, dimethylamine, dioctylamine and other related compounds are present in the "black ooze" as well as in Well GW-2 (See Figure 2). This was determined by an analysis performed by Olin. Mr. Vaughn was very hesitant to have Well GW-2 sampled. He stated that he knew the well was contaminated and Olin was prepared to perform remedial actions of an undisclosed nature to rectify the situation.

The drainage ditch mentioned above has been the object of sampling and analysis on several occasions. On January 23, 1980, five samples were collected by the EPA and subsequently analyzed for purgeable organics. The results indicated the following:

 Moderate to high levels of 1,1 - dichloroethane, 1,1,1 trichloroethane, trichloroethylene, toluene and xylene are present upstream of Stepan/Olin.



Figure 9 - Sheen resulting from "black ooze" seeping into the Drainage Ditch.

- 3.4 Hazards Identified or Alleged continued
 - 2. Moderate to high levels of 1,1,2 dichloroethylene and 1,1,2 trichloroethane in addition to the five chemicals listed under (1) are present downstream of Stepan/Olin.
 - 3. Therefore, some chlorinated hydrocarbons may be leaching from Stepan/Olin into the drainage ditch.
 - 4. Analyses of the outfalls from Stepan/Olin do not indicate significant off-site migration of contamination.

Priority pollutant samples were taken from the drainage ditch paralleling the railroad tracks on July 28, 1980. Analyses of samples taken upstream and downstream of the Stepan/Olin property suggested that small amounts of the priority pollutants listed in Table 2 are generating from the site.

The primary purpose of this site inspection was to gather appropriate samples for analysis to determine if any ground or surface water contamination is generating from Olin property. The sampling plan is presented in Section 4, and the sampling procedures and screening results are included in Section 7.2 of this report. The preliminary results indicate that, with the exception of the "black ooze" and significant amounts of residual heavy hydrocarbons noted in Section 7.2, no significant sources of contamination are present on site. Evidence of buried drums was noted just west of the headwall (See Figure 2). However soil, surface water and groundwater revealed no evidence of hazardous chemicals generating from the burial site.

4. <u>Concept of Operation:</u>

A seven-person team entered this site to identify the nature of materials stored on site, investigate possible sources of contamination and collect appropriate samples for screening and analysis.

Table 2:

Priority Pollutants Suggested To Be Entering the East Drainage Ditch from Olin Property (Based on July 28, 1980 Priority Pollutant analyses)

CONTAMINANT METHOD OF CONTACT HEALTH EFFECTS

<u>Trichloroethylene</u> Inhalation: Headache, nausea, drowsiness

Chronic Inhalation: Possibly liver damage.

(This has not been documented in Humans).

Inhalation of large May cause narcosis

quantities:

Ingestion: Possibly liver damage.

(This has not been documented in humans).

Note: TCE is an experimental animal carcinogen. (rats).

1979 recommended ambient water quality criterion 2ug/l Based on tumors in rats and not on human health affects.

N-Nitrosodiphenylamine Inqestion only Not an inhalation hazard.

Toxicity: This compound belongs to the class of

nitrosamines.

Note: Nitrosamines are suspected human carcinogens. There are no human data, but nitrosamines do cause tumors of the stomach, lung, liver, bladder and kidney in

rats. The class criterion is 0.1/ug/l water (ambient water) based on tumor

formation in rats.

Bis (2-Ethyl hexyl) phthalate

Note: Phthalates are non-biodegradable and potential aquatic hazards. They have no

documented human health effects that may be associated with environmental hazards.

Phthalates are used as plasticizers in latex materials and are often used in medical

equipment such as IV infusion sets.

Phthalates may leach off of such equipment and are suspected in the etiology of

shock lung syndrome when injected intraveneously.

1,1,2 - Trichloroethane Toxicity - Inhalation: Narcotic, local irritant may (B -

cause liver and kidney damage.

Ingestion: Local irritant (in 1 ug/l concentrations)

suspected to cause liver and kidney damage

It may be a percutaneous hazard - when hands are immersed in concentrated liquid

(only).

1,2 - trans-Dichloroethylene Toxicity: low toxicity except when exposed to

concentrated vapor - nausea, vomiting,

dizziness with immediate recovery upon removal

from exposure.

Ingestion: Ingestion of concentrated liquid - hausea,

vomiting.

1,2 - DCE is a dermatitis producing agent. It is not percutaneous.

Vinyl Chloride:

Note:

Note:

Note: A well-known human carcinogen. 1979 ambient WQ criterian = 51 ug /l based on

tumor-production in rats

4. <u>Concept of Operation</u> - continued

The following instruments were used during the visit to delineate potentially hazardous areas and screen samples:

- 1. Century organic vapor analyzer (OVA)
- 2. Explosimeter
- 3. Oxygen meter

The site sampling plan was based upon existing knowledge of groundwater and surface water movement on Olin property. The groundwater contours presented on the overlay for Figure 10 are from a report entitled "Report on Groundwater and Surface Water Study -Stepan Chemical Company, Wilmington, Massachusetts" by Geotechnical Engineers, Inc. of Winchester, Massachusetts (1979). Both groundwater and surface water moves in a northwest to southeast direction. As a result, priority pollutant groundwater and surface water samples were taken near the southeast corner of the site. A priority pollutant groundwater sample was taken near the northwest corner of the site for background data. A total of eight groundwater, ten surface water and five soil samples were taken. The sampling locations are shown in Figure 10. See Section 7.2 of this report for detailed sampling procedures and preliminary screening results. Parameters for the monitoring wells on Olin property are presented in Table 2.

All samples were iced immediately and brought to the EPA Regional Laboratory in Lexington, Massachusetts, for further screening and analysis. Appropriate decontamination measures were followed prior to leaving the site. The safety plan and report are included in Appendix A.




TABLE 3 - Parameters for Monitoring Wells on the Olin Property in Wilmington, Massachusetts

	Depth of Well	Water Table	Depth of Screened
<u>Well #</u>	<u>(ft.)</u>	Depth (ft.)	Section (ft.)
GW - 1	21 2	0.0	140 10 5
GW - 1	21.2	9.0	14.0 - 19.5
GW - 2	15.0	7.5	9.5 - 14.5
GW - 3	22.0	4.2	10.0 - 15.0
GW - 4	13.5	2.5	8.0 - 13.0
GW - 5	12.0	0	5.0 - 10.0
GW - 6	18.0	4.0	8.2 - 13.2
GW - 7	14.0	2.6	8.5 - 13.5
GW - 8	10.2	1.5	3.2 - 8.2
GW -10	24.0	5.4	4.8 - 9.8
GW -11	17.0	3.9	9.0 - 14.0
GW -12	12.7	0	4.8 - 9.8

- All wells have inside diameters of 1.5".
- Location of wells is shown in Figure 2 of this report.
- All well parameters are from: Report on Groundwater and Surface Water Study Stepan Chemical Company, Wilmington, Massachusetts: Geotechnical Engineers, Inc. Winchester, Massachusetts, December 6, 1978.

F1-8005-01F

5. Logistics and Site Setup:

Because of the large area covered during this inspection and the large amount of sampling equipment required to accomplish the objective, it was necessary to move the van and associated decon several times. Figure 11 shows the various locations of the van during the inspection. Equipment decontamination was performed after each sampling effort, and appropriate equipment and personnel decontamination measures were performed following the final sampling at Well GW-2 (Station 012).

No hot line was delineated as no "hot spots" were indicated during the preliminary assessment or the site inspection.

No logistical problems were encountered during the planning and performance of this site inspection. A minor pumping problem was encountered during sampling at the first groundwater station (001). However, following appropriate adjustments, samples were successfully retrieved from depths up to ten feet with the portable hand pump. The portability of this sampling technique was very important at Station 008 which was nearly inaccessible due to dense vegetation and swampy ground.

6. Site entry team and Schedule of Events:


6.1 Site Entry Team and Team Assignments:

David Cook - Site Entry Team Leader

Paul Clay - Sampling Officer
Lori Fucarile - Safety Officer

Glenn Smart - Equipment/Work Party

Richard DiNitto - Work Party
Margret Hanley - Work Party
Bill Norman - Work Party



6. Site Entry Team and Schedule of Events - continued

6.2 Schedule of Events

The site entry team was briefed by the team leader on November 11, 1980 (the day before site entry). The briefing included review of appropriate data obtained during the preliminary assessment for the purpose of making the team aware of all potential hazards. The briefing focused the team's attention on the questions raised by the preliminary site assessment.

In order to facilitate completion of sampling on November 12, 1980, the team was divided into two groups: Cook, DiNitto and Hanley (Team 1) collected the surface water and sediment samples and Fucarile, Clay, Smart and Norman (Team 2) collected the groundwater samples.

The following was the schedule of events for the site inspection.

- 0900 Van arrives at Olin, team sets up decon and prepares sampling equipment. D. Cook meets with Olin representatives (Ted Groom and M. Ahsah of Olin Research Laboratory, David Vaughn, Environmental Coordinator and Ron McBrien, Plant Manager) and explains the objectives of the inspection. Split samples and duplicate photos are requested by McBrien and Vaughn.
- 0930 Smart and Clay sample Well GW-1 (Station 001, Sample #70818).
- 1038 Smart and Clay collect priority pollutant sample at Well GW-5 (Station 002, Sample #70809).
- 1040 Cook collects priority pollutant sample of surface water at outlet of on-site drainage ditch (Station 003, Sample #70803).

6. Site Entry Team and Schedule of Events

- 6.2 Schedule of Events continued
 - 1100 Clay samples culvert from E. C. Whitney (Station 004, Sample #70814).
 - 1105 Clay samples surface water from North Drainage Ditch (Station 005, Sample #70815).
 - 1140 Smart and Clay collect priority pollutant sample from Well GW-10 (Station 006, Sample #70816).
 - 1200 Team breaks for lunch and discusses sampling completed and still to be completed.
 - 1315 Team returns to site and divides into two groups described earlier (Teams 1 & 2).

Team 2:

- 1330 Smart and Norman sample Well GW-12 (Station 007, Sample #70825).
- 1400 Smart, Clay and Norman sample Well GW-8 (Station 008, Sample #70826).
- 1430 Smart, Clay and Norman sample Well GW-11 (Station 009, Sample #70827).
- 1505 Norman and Smart sample Well GW-6 (Station 010, Sample #70828).
- 1530 Clay, Smart and Norman attempt to sample Well GW-7 (Station Oll) but are foiled by a wasps' nest in the well.
- 1545 Team 2 samples Well GW 2 (Station 012, Sample #70812).

6. Site Entry Team and Schedule of Events

6.2 Schedule of Events - continued

Team 1:

- 1330 Sediment sample taken with auger at sulfate sludge landfill (Station 100, Sample #70824).
- 1345 Sediment and surface water samples taken on Jewel Industrial Park property just west of culvert leading to Olin property (Station 101, Sample #70817).
- 1355 Sediment and surface water samples taken at culvert just south of the Lagoon 2 (Station 102, Sample #70807).
- 1420 Surface water sample taken approximately 75 feet east of Well GW-12 (Station 103, Sample #70821).
- 1440 Surface water sample taken at west end of Central Pond (Station 104, Sample #70822).
- 1500 Surface water sample taken at east end of Central Pond (Station 105, Sample #70823).
- 1515 Sediment and surface water samples taken in area of dead trees (Station 106, Sample #99999).
- 1530 Soil sample taken where Lake Poly was formerly located (Station 107, Sample #70808).
- 1540 Surface water taken near headwell (Station 108, Sample #70810).
- 1550 Evidence of buried drums (rusted bands lids and two partially buried drums) noted just west of headwall. Shallow soil sample collected (Station 109, Sample #9998).
- 1610 Soil sample taken from area just south of tank farm (Station 110, Sample #99997).

6. Site Entry Team and Schedule of Events

6.2 Schedule of Events - continued

Team 1:

1615 - Teams 1 and 2 reunite at van and proceed to decon personnel and equipment. Chain of custody forms are completed and D. Vaughn of Olin signs for split samples transferred to him.

1640 - Site Inspection completed, team returns to office.

7. Results of Investigation

7.1 Site Representative Interview:

A detailed interview regarding the processes used on site was not necessary as this information was gathered during the preliminary assessment and is incorporated into Section 3.2 of this report. Mr. David Vaughn, Environmental Coordinator for Olin Chemicals Group, did confirm the presence of dioctylphthalate, diphenolamine, dioctylamine and other related chemicals in the "black ooze" seeping into the East Drainage Ditch. The seepage appears to be the result of a spill generating from the tank farm which took place during or prior to 1973. Presented in Appendix C is a letter from Charles P. Riley, Jr., General Manager of National Polychemicals to Thomas C. McMahon, Director of Massachusetts Water Resources Commission, dated July 18, 1973, describing the presence of "black ooze". Mr. Vaughn also confirmed the presence of contamination in Well GW-2 related to this spill and was hesitant to have us sample this well prior to undisclosed remedial action planned by Olin.

Mr. Vaughn expressed his desire to obtain duplicate samples and photographs associated with the site inspection.

7. Results of Investigation - continued


7.2 Sampling procedures and screening results:

7.2.1 Groundwater sampling procedures

The preparation for sampling the monitoring wells on the Olin property was the same in each case: (Note: All wells were capped and bolted. The bolts were sawed off to remove the well cap.)

First, the static level of water in the well was determined with a water level indicator. Second, the bottom of the well was sounded. using these two measurements and the diameter of the well casing (1 1/2", in each case), the static volume of water in the well was calculated. Third, a hand operated vacuum pump attached to a sufficient length of Tygon tubing was used to discharge five times the static volume of the well. (This amount of discharge was not possible in some wells because of slow recharge and silted-in screens.) Following discharge, a volume of sample appropriate for the desired analytical parameters was collected by pumping. E & E personnel first filled their bottles and then filled bottles for Olin sampling personnel.

Between the sampling of each well, the sampling line and pump was cleaned by rinsing thoroughly, first with methanol and then with distilled water. The E & E sampling crew consisted of Paul Clay and Glenn Smart for wells GW-1, 5, and 10 and Paul Clay, Glenn Smart and William Norman for wells GW-12 8, 11, 6, 7, and 2. A groundwater elevation contour map prepared from data gathered during sampling is presented in Figure 12, which is very similar to Figure 10, the groundwater elevation contour map prepared by Geotechnical Engineers. The major difference is that surface of the the water table was generally 1 1/2 to 2 feet lower at the time of the E & E site inspection.



- 7.2 Sampling procedures and screening results:
 - 7.2.1 Groundwater sampling procedures continued

The following is a summary of the sampling operations and data obtained at each well:

<u>Olin Well GW-1</u> (Station 001, Sample #70818):

Depth of well: 21' 4"

Depth to water (static level): 11' 4"

Volume purged prior to sampling: 5 gallons

Samples taken: E & E obtained (1) 40 ml VOA vial with 10% head space for screening. Olin representatives obtained 80 ml.

Olin Well GW-5 (Station 002, Sample #70809):

Depth of well: 13' 2 1/2"

Depth to water (static level): 4' 1"

Volume purged prior to sampling: 5 gallons

Samples taken: E & E obtained the following priority pollutant sample:

- (2) 1/2 gallon jars with Teflon lined caps for extractables
- (2) 40 ml VOA vials for purgeables
- (1) 1 liter polyethylene bottle for metals
- (1) 40 ml VOA vial with headspace for screening Olin representatives obtained similar volumes for similar analyses.

<u>Olin Well GW-10</u> (Station 006, Sample #70816):

Depth of well: 12' 3"

Depth to water (Static level): 8'7"

Volume purged prior to sampling: 3 1/2 gallons

Samples taken: E & E obtained sufficient volume in appropriate containers for priority pollutant

- 7.2 Sampling procedures and screening results:
 - 7.2.1 Groundwater sampling procedures continued

analyses (See description under Well GW-5).
Olin representatives obtained similar volumes for
 analyses.

<u>Olin Well GW-12</u> (Station 007, Sample #70825):

Depth of well: 12' 1"

Depth to water (static level): 4' 7"

Volume purged prior to sampling: 3 1/2 gallons

Samples taken: E & E obtained (1) 40 ml VOA vial with 10% head space for screening. Olin representatives obtained 80 ml.

Note: Due to the fact that leaves and other debris were pumped as this well was purged, it is likely that the well casing is broken below the water table.

Olin Well GW-8 (Station 008, Sample #70826):

Depth of well: 10'10"

Depth to water (static level): 5'1"

Volume purged prior to sampling: 3 1/2 gallons

Samples taken: E & E obtained (1) 40 ml VOA vial with 10% headspace for screening. Olin representatives obtained 80 ml.

Note: Water had a brown, murky color throughout the purging and sampling processes.

<u>Olin Well GW-11</u> (Station 009, Sample #70827):

Depth of well: 15' 9"

Depth to water (static level): 6'3"

Volume purged prior to sampling: 3 1/2 gallons

Samples taken: E & E obtained (1) ml VOA vial with 10% head space for screening. Olin representatives obtained 80 ml.

- 7.2 Sampling procedures and screening results:
 - 7.2.1 Groundwater sampling procedures continued

Olin Well GW-6 (Station O10, Sample #70828):

Depth of well: 15' 1"

Depth to water (Static level): 5'11"

Volume purged prior to sampling: 3 1/2 gallons

Samples taken: E & E obtained (1) 40 ml VOA vial with 10% head space for screening. Olin representatives obtained 80 ml.

Olin Well GW-7 (Station Oll, Sample #70811):

Depth of well: 16' 0"

Depth to water (static level): 5'4"

Volume purged prior to sampling: under two gallons

Samples taken: No samples taken.

Note: Well was clogged with wasps.

Olin Well GW-2 (Station Ol2, Sample #70812)

Depth of well: 16' 9"

Depth to water (static level): 12' 5"

Note: This well was highly contaminated with an oily substance, most likely dioctylphthalate.

Volume prior to sampling: Because of the depth of the well and the high viscosity of the contaminant, it was not possible to obtain more than a quart of material from this well. The intent was to take sufficient volume for a priority pollutant analysis. The volume obtained was split with Olin representatives. The sample was very obviously two-phase, with a top dark brown layer and a bottom aqueous layer.

- 7.2 Sampling procedures and screening results:
 - 7.2.2 Surface water and sediment sampling procedures:

With the exception of the priority pollutant surface water sample collected at Station 003, all sediment and surface water samples consisted of (1) 40 ml VOA vial with head space. All sediment samples were collected with a four-inch diameter soil auger. The locations of all sampling stations are shown in Figure 10.

Station 100 - Sample #70824

A sample from the sulfate sludge landfill was taken approximately one foot below the surface. The sample was greyish-white in color and had the consistency of wet clay.

Station 101 - Sample #70817

A mucky sediment sample was taken in the drainage channel approximately six inches below the channel bottom. A surface water sample was also collected at this station. The water was clear and colorless.

Station 102 - Sample #70807

A surface water sample was initially taken. Upon seeing a bubble of material breakout onto the water surface in a rainbow - colored sheen, it was decided to take a sediment sample. The sediment sample was taken approximately six inches below the channel bottom. It was black and impregnated with a thick black oily substance. A heavy rainbow-colored sheen covered the entire drainage channel as oily material seeped to the surface of the water from the hole made by the auger. Another surface water sample was subsequently taken. The water was clear and slightly brownish in color.

Station 103 - Sample #70821

A surface water sample was taken from a large puddle of standing water located in a depression resulting from recent (?) earth movement. The water was clear and colorless.

- 7.2 Sampling procedures and screening results:
 - 7.2.2 Surface water and sediment sampling procedures:

Station 104 - Sample #70822

A surface water sample was taken. The water was clear and colorless.

Station 105 - Sample #70823

A surface water sample was taken. The water was clear and colorless.

Station 106 - Sample #99999

A black mucky sediment sample was taken approximately six inches below the surface. The auger hole was allowed to recharge with water and a water sample was subsequently taken. The water was clear and colorless.

Station 107 - Sample #70808

A surface water sample was taken. The water was clear and colorless and was moving swiftly in the channel.

Station 108 - Sample #70810

A sandy, grey-colored, water soaked sediment sample was taken approximately four feet below the ground surface. Material above the sample location was light-tan, coarse grained sand.

Station 109 - Sample #99998

A black, mucky sediment sample was taken approximately six inches below the surface. The entire area where this sample was taken was resilient when jumped upon. The collected sample had the odor of fuel oil.

<u>Station 110</u> - Sample #99997

A dark, fine-grained soil sample was collected approximately six inches below the ground surface.

7.2 Sampling procedures and screening results:

7.2.2 Surface water and sediment sampling procedures:

Station 003 - Sample #70803

A priority pollutant sample was taken of the surface water. There was a thin sheen on the surface of the water. The water was clear and colorless.

Station 004 - Sample #70814

A sample was taken of the standing water at the outlet of the culvert. The water which was clear and colorless was covered with the thick sheen.

Station 005 - Sample #70815

A sample was taken of the surface water. It was clear and colorless.

7.2.3 Screening results of surface water and groundwater samples

The samples specified below were screened on a Century Portable Gas Chromatograph using a T-12 column. All samples were shaken vigorously for two minutes and allowed to reach ambient temperature. 250 microliters (ul) of the headspace vapor were then withdrawn and injected directly into the detector to measure the total volatile hydrocarbon content. Those samples showing volatiles were then run again, but in the gas chromatograph mode. The results follow:

Olin Well GW-1 - Sample #70818

Large methane peak, followed by smaller, fast second peak - unidentified, possibly a higher alkane

Olin Well GW-5 - Sample #70809

Methane peak, no other volatiles within detection limit pH of sample = 6-8. Sample submitted for priority pollutant analysis.

Olin Well GW-10 - Sample #70816

Large methane peak, followed by smaller, fast second peak - unidentified, possibly a higher alkane. Sample submitted for priority pollutant analysis.

7. Results of Investigation

- 7.2 Sampling procedures and screening results continued
 7.2.3 Screening results of surface water and groundwater samples
 - Olin Well GW-12 Sample #70825

 No volatiles present within detection limits. pH of sample = 6-8.
 - Olin Well GW-8 Sample #70826

 No volatiles present within detection limits. pH of sample 4-6.
 - Olin Well GW-11 Sample #70827

 Large methane peak, followed by smaller, fast second peak
 unidentified, possibly a higher alkane.
 - Olin Well GW-6 Sample #70828

 Methane peak, followed by small fast peak unidentified, possibly a higher alkane.
 - Olin Well GW-7 Not analyzed
 No sample obtained
 - Olin Well GW-2 Not analyzed
 Olin has confirmed presence of dioctylphthalate in the well.
 - Olin/West End of Central Pond Sample #70822 No volatiles within detection limits. pH = 6-8
 - Olin/Jewel Drive side of culvert Sample #70817

 No volatiles within detection limits. pH = 6-8
 - Olin/Channel near well #5 Sample #70803

 Methane, then very small second peak not identified.

 Sample submitted for priority pollutant analysis.

7. Results of Investigation

- 7.2 Sampling procedures and screening results continued7.2.3 Screening results of surface water and groundwater samples
 - Olin/Culvert southeast of sulfate lagoon Sample #70807 Methane, then very small second peak - not identified.
 - Olin/East End of Central pond Sample #70823

 No volatiles present within detection limits. pH of sample 6-8.
 - Olin/Non Contact Cooling Water west end of warehouse Sample #70810

 Methane present.
 - Olin/North Drainage Ditch Sample #70815

 Methane present. No other volatiles within detection limit. pH = 6-8.
 - Olin Standing Water near Well GW-12 Sample #70821

 No volatiles present within detection limits. pH = 6-8
 - Olin/Surface Water near vegetative stress area Sample #99999

 No volatiles present within detection limits. pH = 6-8.
 - 7.2.4 Screening results of soil and sediment samples.

An attempt will be made to analyze for the presence of volatile vapors in these samples by allowing the samples to reach room temperature and injecting a portion of the head space vapor into the portable GC. Since the column of the portable GC operates at ambient temperature, it is not practical to heat up the sediment samples to drive off vapor, as the vapor might condense in the column and thereby destroy the column.

7. Results of Investigation

- 7.2 Sampling procedures and screening results continued
 - 7.2.5 Photographs of Sampling Points

Figures 13 through 30 are photographs of the sampling locations.

8. Recommendations:

E & E has made arrangements with Olin to collect a priority pollutant sample at Well GW-2 to determine the extent of contamination. A pump capable of sampling this well is on order. With this exception, no additional on-site inspection or sampling activity of this site is warranted at this time. Should the priority pollutant analyses indicate unanticipated contamination, the need for re-entry will be evaluated.

The East Drainage Ditch should be examined regularly to determine if the absorbant pads now in place are preventing the entry of phthalates, amines and phenols into the ditch. There is an obvious need for remedial action to eliminate the ongoing contamination of a Class B stream (East Drainage Ditch) with priority pollutants including dioctylphthalate and possibly diphenyl hydrazine as well as various phenols and amines.

To avoid repeated spills of hazardous materials from the tank farm, it is recommended that an impervious base and confinement structure be provided.

The release of heavy fuel oil from oil impregnated soil into the North Drainage Ditch is taking place. The placing of absorbant pads at the entrance of this ditch into the East Drainage Ditch is recommended.

9. Conclusions:

The seepage from Olin property of at least one priority pollutant (dioctylphthalate) into a Class B stream is presently occurring.

This contamination is very likely entering the Aberjona River by way of Halls' Brook Storage Area.

A monitoring well located on Olin property is grossly contaminated with at least one priority pollutant.

There is extensive contamination of soil on Olin property with heavy residual oil.

A completed Potential Hazardous Waste Site - Site Inspection Report is included in Appendix B.



Figure 13: Sampling Station 001



Figure 14: Sampling Station 002




Figure 15: Sampling Station 003



Figure 16: Sampling Station 004




Figure 17: Sampling Station 005



Figure 18: Sampling Station 006




Figure 19: Sampling Station 007



Figure 20: Sampling Station 008




Figure 21: Sampling Station 009




Figure 22: Sampling Station 010



Figure 23: Sampling Station 012



Figure 24: Sampling Station 102




Figure 25: Sampling Station 103




Figure 26: Sampling Station 104




Figure 27: Sampling Station 105



Figure 28: Sampling Station 106



Figure 29: View toward the northwest from Sampling Station 106




Figure 30: Sampling Station 108

APPENDIX A

SITE SAFETY PLAN

and

REPORT

SITE SAFETY PLAN

* * * · · · · · · · · · · · · · · · · ·	•	
TE: Olin Chemicals Group Plant	DATE: 10/23/80	TDD #:1-8005-01
CATION: Eames Street, Wilmington, MA		
VESTIGATIVE OBJECTIVE(S): To gather information	ation necessary to determine th	e potential for RCRA
and/or 311/104 Clean Water Act action		
		
CKGROUND REVIEW: Complete: x Pr	reliminary:	
· · · · · · · · · · · · · · · · · · ·	erious Moderate x	Low Unknow
•		•
SITE/	WASTE CHARACTERISTICS	
STE TYPE(S): Liquid \underline{x} Solid \underline{x} Sli	udge _x Gas	
ARACTERISTIC(S): Corrosive_x Ignitable_ Rac		React. Unk. Oth
CILITY DESCRIPTION: Size: 53 acres		
11 storage tanks, 12 wells	•	
Topography: embankment to ditch at RR to		
Principal Disposal method (type and loc	ation): formerly three acid	perty
settling basins used for gypsum containment,	storage tanks	ous, now rectangular
Unusual Features (dike integrity, power		and her DOM DD to the
5.10502. (5.105.65 (5.105.65), pend.	Status: (open, clos	
STORY: (worker or non-worker injury; complai		
Analysis of sludge Nat'l Polychemicals, Inc.		· · · · · · · · · · · · · · · · · · ·
Engineers Study PVC liner leaks in 1979, Com	plaints to MDC regarding high	ghlorido gulfato
and ammonia levels in sewer. Former Stepan	employee unofficially reported	Phosphores Laborate
dumped on ground and residues buried near we		
because he was overcome by ammonia fumes ins		cal for oxygen
	ARD EVALUATION	
· · · · · · · · · · · · · · · · · · ·		
Moderate Hazard, After close examination of The only priority pollutants presumed to be	on site are toluene and distance	chemical Study etc.
highly likely that toluene would have volati	lized soon often a settle. Die	Iphalate. It is
a vapor hazard. Toluene could be a vapor haz	zard if it is leaking. Ultra t	ctylphalate is not
Also, could have acidic or basic leachates the	his rubber gloves and hart-	wins should be worn.
Eve protection taken care of by Ultra This -	ats Other groves and boots and	apron protection.
Eye protection taken care of by Ultra Twin make be on site could be ingestion hazards; there	fore reasonable bygons should	itants which may
and the state of t	tore, reasonable hygene should	De practiced.
	· ·	
	·	
	· · · · · · · · · · · · · · · · · · ·	
-		<u>;</u>
		.~ .
reckeled baber	econiggyand from the	RP1: IRC

FCOLOGY AND ENVIRONMENT, INC.

FIELD INVESTIGATION TEAM - REGION I

WORK PLAN INSTRUCTIONS

DEDI	METER ESTABLISHMENT: Map/Sketch Attached _x ^C Site Control
	ublic Perimeter Identified X Zone(s) of Contamination Identified X
	OTES:
iv	0163.
c a	reas of special safety concern identified
	ONAL CLOTHING:
	evel of Protection: A B C x D
M	odifications:
	odifications:
S	urveillance Equipment and Materials: TLD badges
	The badges
DECÕI	NTAMINATION PROCEDURES:
Н	ot Line Location (initial): at public perimeter access
	ommand Post Location (initial): at public perimeter access
	OS Stations: 1. boot & glove wash 2. boot & glove rinse
3.	4. 5.
· E0	quipment and Materials/Special Facilities:
TITE	ENTRY PROCEDURES:
	eam Size: E & E 5 State Other
	ntry Briefing (date) day before site entry
	tation Designation (name/responsibility): 1
2.	
4.	
6.	
	ork Schedule/Limitations:
-	
	Site entry team will not be entering any buildings. Entry to (outside) area will be do
	only after receiving permission from Olin Chemical.

FIELD INVESTIGATION TEAM - REGION I

DRK PLAN INSTRUCTIONS - continued

EMERGENCY PRECAUTIONS:

ACUTE EXPOSURE SYMPTOMS	FIRST AID
Volatile hydrocarbon exposure: lightheadedness, nausea	Get to fresh air, administer
-	oxygen if required. Seek
	medical aid
HOSPITALS/POISON CONTROL CENTERS (address, telephone number	r)
See Resources List	
EMERGENCY TRANSPORTATION SYSTEMS (Fire, police, ambulance)	
See Resources List	
EMEDOCANON DOUTES	
EMERGENCY ROUTES	
Choate Hospital, Left from Olin gate onto Eames St. to Rou	
straight (Under 128) to Woburn Center approx 1.5 miles to	Warren Ave. Choate Hospital is
at top of hill.	
	· · · · · · · · · · · · · · · · · · ·
EQUIPMENT CHECKOUT	,
· · · · · · · · · · · · · · · · · · ·	
SCBA Cylinders	Eye Wash Unit x
Ultratwin x Cartridges x	First Aid Kit x
Explosimeter x	Drinking Water Supply x
O ₂ Indicator x	Personal Clothing x
Draeger Pump x Tubes x	Decontamination Mat'ls. x
Radiation Survey Meter	
Radiation Contamination Meter X	ecology and environment, inc.

ECOLOGY AND ENVIRONMENT, INC. LIELD INVESTIGATION TEAM - REG. LA I

SITE SAFETY PLAN SUMMARY

NAME OF SITE	: Olin Chemical Gr	roup	· DATE: 10/23/80
TDD #:	F-1-8005-01F		
Location of	site: Eames Street	t, Wilming	ton, MA
Directions t	O site: Washington Way, right	Street No	rth to West Street. Left on Industri
Project Lead	er/Site Entry Leade	r: David	Cook
Safety Person	n: Lori Fucaril	Le	
Equipment Per	rson: Paul Clay		
		David Cook	, Palermo, Paul Exner
Reason for S	ite Entry: <u>to dete</u>	ermine pot	ential for RCRA/311/104 action
·	1		
Special Hazar	rds: Volatile hydro	ocarbons m	ay be present; acid or base may be pr
Special Hazar	rds: Volatile hydro	carbons m	ay be present; acid or base may be pr
Special Hazar	rds: Volatile hydro	ocarbons m	ay be present; acid or base may be pr
	· ·		ay be present; acid or base may be pr
	· ·		
lazard Assess	· ·		
lazard Assess	· ·		
lazard Assess expected	· ·		
lazard Assess expected	sment: (H, <u>M</u> , L, Unk		
lazard Assess expected	sment: (H, <u>M</u> , L, Unk		ate, High levels of contaminants not
dazard Assessexpected	sment: (H, <u>M</u> , L, Unk		ate, High levels of contaminants not
Sazard Assess expected evel of Prot	ement: (H, M, L, Unk		ate, High levels of contaminants not
dazard Assessexpected evel of Protection Required Protection 1. Ultra	ection: Level C	(.) Moder	ate, High levels of contaminants not
Required Prot	ment: (H, M, L, Unk ection: Level C etective Equipment:	(.) Modera	ate, High levels of contaminants not
expected evel of Prot Required Prot 1. Ultra 3. Tyveks	ection: Level C tective Equipment: Twin w/cartridge (Chem. Resistant)	(.) Moder:	Robert Shaw

....anlggyaandeenyiranmantsiing.

receseveles paper

DATE: 10/23/80

SITE: Olin Chemical Group Plant

TDD #: F-1-8005-01F

(locate resources on area map)

•	NAME	<u>. TO</u>	NWC		PHONE	NOTIFIED YES/NO
FIRE	Wilmington	Wilmi	ngton		658-3200	no
POLICE	Wilmington		ngton		658-3200	no
AMBULANCE	Wilmington		ngton		658-3200	no
HOSPITAL ER	Choate Hospital	Warren	Ave., Woburn		933-6700	no
ATER SUPPLY	on van					•
TELEPHONE	Olin Chemical	Eames	St, Wilmingt	on, MA	933-4240	yes
RADIO COMMUNICATIONS	·NA					
AIRPORT	NA					
HELIPORT, AREA	NA		······································			
EXPLOSIVES UNIT	State Police	S. Ly	nnfield		593-1122	no
EPA CONTACT	Rick Leighton	Lexir	ngton/NERL		861-6700	yes
LIST OTHER RESOURCES:						
					1	
		EMERGENCY NUMB	<u>ERS</u>		· · · · · · · · · · · · · · · · · · ·	
E & E, Inc., Woburn		(617) 935-0228	(0238)	(4008)	
E & E, Inc. Arlington	n, VA	(703	522-6065		number - call forwarding	
Dr. Harbison - Vander	bilt	(615	322-4754			•
Dr. Harbison - home		(615	747-6353	24 hr.	number - 9 second message	
Robert Young - home		(617	,		1	
Anne Marie Desmarais		(617) 897-5306			
Peter Bent Brigham, O	ccup. Ind. Health	Clinic:				
Dr. Speizer, Dr. S) 732-5983			
24 hour number - a	sk for hellboy 90	4 (617	732-6000			
						

ECOLOGY AND ENVIRONMENT, INC. F.__D INVESTIGATION TEAM - REGION .

SITE SAFETY REPORT

NAME OF SITE: _	Olin Ch	emicals Group	DATE	OF ENT	RY: 11/1	2/80
TDD #:	F-1-800	5-01F	·· — —			
Reason for Site	Entry:	To obtain information	and samp	les fo	r possible	e RCRA
	-	and/or 311/104 Clean W Chemicals Group.	ater Act	actio	ns regardi	tng Olin
Personnel on Si	te:		•			
Site Entry L	eader:	David Cook				
Safety Perso	n:	Lori Fucarile				
Equipment Pe						
Work Party:_		Paul Clay, Glenn Smart	, Margrei	Hanl	ey, Richar	d DiNit
Other E & E	Personne	el:		yanin name		
Othan Dancan	nol on C	ito				_
Uther Person	nei on s	ite: Ted Groom, M. Ah	sah, and	D.Vau	ghn (Olin	Research
				·		
Explain Any YES	Answer	on an Attached Sheet:		 	YES	NO
1 Was the Saf	aty Dlar	followed as presented	2			
		deviations in full.	•		x	
Explain any	and an	deviations in full.		,		
2. Did any tea	m member	report chemical expos	ure?			<u> </u>
Did any tea unusual sym		report illness, disco	mfort, o	r		<u>x</u>
4. Did any tea (heat, cold		report environmental	problems	?		x
5. Did any tea	m member	report injury?			***************************************	X
6. Did the sit (rain, lack		have to be curtailed for etc.)	or <u>any</u> re	eason?		X
7. Were any em	ergency	services or resources	utilized	?		x_
8. Were there	any unus	ual occurences?				<u> </u>
9. Was the Saf	ety Plan	adequate?	· .		. <u> </u>	
0. What change	s would	you recommend? None				
	 -					

APPENDIX B

POTENTIAL HAZARDOUS WASTE SITE

SITE INSPECTION REPORT



POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

REGION	CITE	NUMBER	(to	ha	appide
KEGION	1311	1101110 -11	(-	agg.g.i
	ed by	, Hal			
	,,				
	1				

Ι

GENERAL INSTRUCTIONS: Complete Sections I and III through XV of this form as completely as possible. Then use the information on this form to develop a Tentative Disposition (Section II). File this form in its entirety in the regional Hazardous Waste Log File. Be sure to include all appropriate Supplemental Reports in the file. Submit a copy of the forms to: U.S. Environmental Protection Agency; Site Tracking System; Hazardous Waste Enforcement Tack Force (EN-335); 401 M St., SW; Washington, DC 20460.

	I. SITE IDEI	NTIFICATI	ON		,
A. SITE NAME		B. STREET	(or other identifier)	439	,
Olin Chemicals Group-W	ilmington Plant	Eame	s Street		,
C. CITY			E. ZIP CODE	TF. COUNTY NA	ME
Wilmington		MA	01887	Middlese	·v
Wilmington G. SITE OPERATOR INFORMATION		I III	1 01007	Middlese	·A
1. NAME				I 2. TELEPHON	IE NUMBER
				1	
Mr. Ron McBrien (Plant	Manager)			933-4240	·
9. STREET	4. CITY			8. STATE	6. ZIP CODE
Eames Street	Wilmingto	on	•	MA	01887
H. REALTY OWNER INFORMATION					<u> </u>
1. NAME				2. TELEPHON	IE NUMBER
				İ	
N/A					
3. CITY				4. STATE	8. ZIP CODE
I. SITE DESCRIPTION					
Complex of Chemical Pro	ocess Buildings on a	large w	ooded lot		
J. TYPE OF OWNERSHIP	SCORE PULLULINGS OIL U				
1. FEDERAL 2. STAT	TE 3. COUNTY	4. MUNICIP	AL X 5. PRIVA	TF	
	3. 000111	4. MONICH		'-	
					· ·
	II. TENTATIVE DISPOSITION			<u> </u>	
A. ESTIMATE DATE OF TENTATIVE	B. APPARENT SERIOUSNES	S OF PROBI	LEM		
DISPOSITION (mo., day, & yr.)	1. HIGHX	2. MEDIUM	3. LOW	4. NON	E
	1	•			
C. PREPARER INFORMATION		·			
1. NAME		2. TELEP	HONE NUMBER	3. DATE (mo.,	day, & yr.)
	•	005 40	o o	10/4/00	,
David K. Cook	····	935-40		12/4/80	
	III. INSPECTIO	N INFORMA	TION	<u> </u>	
A. PRINCIPAL INSPECTOR INFORMA	ATION				•
1. NAME		2. TITLE		•	
David K. Cook		Sr Gen	logical Engine	er	
3. ORGANIZATION		<u> </u>	100 1001 1110 11V	4. TELEPHON	E NO. (area code & no.)
				617 025 4	^^^
Ecology and Environment	t, Inc. (E&E)			<u> 617-935-4</u>	.008
B. INSPECTION PARTICIPANTS					
1. NAME	2. ORGA	NIZATION		3. TEL	EPHONE NO.
David K. Cook	Ecology and Environ	ment, In	.C.	935-4008	
Paul Clay	Ecology and Environ			935-4008	
			· · · · · · · · · · · · · · · · · · ·	935-4008	
Richard DiNitto	Ecology and Environ			. [
Margret Hanley	Ecology and Environ	ment, In		935-4008	
William Norman Glenn Smart	Ecology and Environ	ment: in	C.	335=4888	•
Lori Fucarile	Ecology and Environ	ment. In		935-4008	
C. SITE REPRESENTATIVES INTERV					
1. NAME	2. TITLE & TELEPHONE NO			. ADDRESS	
David Vaughn	Environmental Coord:	inator	203-356-3156	Hartford	- CT
David Vaugiiii	Environmental cools.	- Inacor			., 0.
Ted Groom	Chemist	<u>_</u>	203-356-3156	Hartford	, CT
					•
M. Ahsah	Chemist 435-4240	1	Wilmington, N	1A	
,					
	•	- 1			
			·		

					91 - 1, 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1

Continued From Front					
		INSPECTION INFORMA	TION (continued)		
D. GENERATOR INFORMATIO					:
1. NAME	2. TELEPHONE	NO.	3. ADDRESS		TYPE GENERATED Is associated
Olin		Wilmington		with rul	ls associate bber blowing anufacture
		·			
	ļ				
			· .		
E. TRANSPORTER/HAULER I	NEORMATION				
1. NAME	2. TELEPHONE	٧٥.	3. ADDRESS	4.WASTE TY	PE TRANSPORTED
N/A					
-				·	
enter sommer og det en en en en en en	langura and an analysis of the second				· Programme of the second
F. IF WASTE IS PROCESSED O	N SITE AND ALSO	SHIPPED TO OTHER SITE	S, IDENTIFY OFF-SITE FA	ACILITIES USED FOR	DISPOSAL
1. NAME	2. TELEPHONE	١٥,	3. ADDRE	:ss	
27 /2					
N/A					
	·				
G. DATE OF INSPECTION (mo., day, & yr.)	1	CTION I. ACCESS GAINE			
11/12/80 J. WEATHER (describe)	0900-1630	X 1. PERMISS	ION 2. WARRA	N C	
Clear/Cold					•
		IV. SAMPLING INFO	RMATION		
A. Mark 'X' for the types of	samples taken and			l lab, other EPA lat	o, contractor,
etc. and estimate when th		vailable.			·
1.SAMPLE TYPE	2.SAMPLE TAKEN		SAMPLE SENT TO:		4. DATE
	(mark 'X')				AVAILABLE
8. GROUNDWATER	x	Regional lab (2	oriority)		1/10/81
b. SURFACE WATER					
21	X	Regional lab (1	oriority)		1/10/81
C. WASTE	.				
					<u> </u>
d. AIR					
e. RUNOFF					. *
6. RUNOFF					
£ SPILL					· ·
					ļ
g. SOIL	x	Regional lab	•		1/10/81
	^A	Regional lab			1, 10, 01
h. VEGETATION					
i. OTHER(specify)					
			<u></u>		<u> </u>
B. FIELD MEASUREMENTS TA	7			3.RESULTS	
1. TYPE	2. Loc	ATION OF MEASUREMENT	•	3. RESOL 13	
Explosivity	Various		Consistent	ly 0	
O, Meter	Various		Consisten	ly 20	
p H	All Well	Samples	6-8		
		,			

	Continued From Page 2						
			IV. SAMPLING INFO	RM.	ATION (continued)		
1	PHOTOS						
'	. TYPE OF PHOTOS			IN C	CUSTODY OF:		
	X a. GROUND X b. AEI	RIA	L E&E				•
D	SITE MAPPED?						
	X YES. SPECIFY LOCATION	OF	MAPS: E&E				
	COORDINATES						
ı	I. LATITUDE (degminsec.)			'	2. LONGITUDE (deg-min-sec.)		
L	42° 31' 50"				71° 9′30"		
			V. SITE INF	OR	MATION		
Α.	SITE STATUS						
t t	X 1. ACTIVE (Those inductrial of nunicipal sites which are being us or waste treatment, storage, or distribute a continuing basis, even if infrequently.)	ed spos	2. INACTIVE (Those sites which no longer receive wastes.)		3. OTHER(specify): (Those sites that include such inc where no regular or continuing use has occurred.)		
Β.	IS GENERATOR ON SITE?			_1			
	1. NO 🗶 2. YES(sp	eci	fy generator's four-digit SIC Code,	:	2821		
<u>_</u>	AREA OF SITE (in a set)		D ARE THERE SUPERIOR		THE CITES	-	
١٠.	AREA OF SITE (in acres)		D. ARE THERE BUILDINGS				Puildings
	53		1. NO X 2. YES	spe	cify): approx. 20 Proce	55	partainda
<u> </u>			V7 - 011 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			<u>. </u>	
7	diana 44 i i		VI. CHARACTERIZATIO		OF SITE ACTIVITY vity by marking 'X' in the appro		
- TI	dicate the major site activity(es)	and details relating to each a	CUV	ity by marking 'A' in the appro	PΓ.	T Table 1
Ĥ	A. TRANSPORTER	×	B. STORER	x	C. TREATER	Ê	D. DISPOSER
	1.RAIL	Г	1.PILE	Т	1. FILTRATION	Г	1. LANDFILL
	2. SHIP		2. SURFACE IMPOUNDMENT		2. INCINERATION	Г	2. LANDFARM
	3. BARGE		3. DRUMS	Т	3. VOLUME REDUCTION		3. OPEN DUMP
	4. TRUCK	×	4. TANK, ABOVE GROUND	T	4. RECYCLING/RECOVERY	х	4. SURFACE IMPOUNDMENT
	S. PIPELINE		5. TANK, BELOW GROUND	×	5. CHEM./PHYS./TREATMENT		5. MIDNIGHT DUMPING
-	6.OTHER(specify):		6.OTHER(specify):	1	6. BIOLOGICAL TREATMENT		6. INCINERATION
		Г	-		7. WASTE OIL REPROCESSING	Г	7. UNDERGROUND INJECTION
		ļ			8. SOLVENT RECOVERY		8.OTHER(specify):
					9.OTHER(specify):	Г	•
	•	l		\vdash		P	ossible buried
						Ι.	rums
				1	•	``	Lans
				1		1	
E.	SUPPLEMENTAL REPORTS: If which Supplemental Reports you I				s listed below, Supplemental Repor	ts	must be completed. Indicate
1. STORAGE 2. INCINERATION 3. LANDFILL 4. SURFACE 5. DEEP WELL							
	6. CHEM/BIO/	'. L	ANDFARM 8. OPEN D	υмι		10	D. RECYCLOR/RECLAIMER
VII. WASTE RELATED INFORMATION							
A. WASTE TYPE							
ΙX	1. LIQUID	2. S	OLID X 3. SLUDGE		☐ 4. GAS		
=	X 1. LIQUID 2. SOLID X 3. SLUDGE 4. GAS						
₽.	WASTE CHARACTERISTICS					_	· · · · · · · · · · · · · · · · · · ·
_	_	, ,	SNITABLE TO SACION	~-	IVE X 4. HIGHLY VOLATILE		•
X				U I	=		
12	S. TOXIC 6. REACTIVE X 7. INERT 8. FLAMMABLE						
_	7						
닏	9. OTHER(specify): WASTE CATEGORIES						
Ĭ	Are records of wastes available?	S	pecify items such as manifests, in	ven	tories, etc. below.		,
	Yes-inventories						

Communical From Front	VIII. HAZARD D	ESCRIPTION (continued)		,
X H. DAMAGE TO FLORA/FAUNA				
Large areas of dead tre	es on Olin propert	У		
				•
	·	·		: !
I. FISH KILL				
•	•			
· · · · · · · · · · · · · · · · · · ·				
		· · · · · · · · · · · · · · · · · · ·		
J. CONTAMINATION OF AIR				
•				
				•
K. NOTICEABLE ODORS			•	·
				·
		V		, ·
				•
	•	•		
X L. CONTAMINATION OF SOIL				
-				·
Seepage of phthalates,	amines & phenols i	nto soil		
			•	
				gradus and the second
•				
M. PROPERTY DAMAGE	·			
		•		
				•
	•			
				·
		•		

Continued From Page 6	VIII. HAZARD DESCRIPTION (continued)
N. FIRE OR EXPLOSION	VIII. HAZARD DESCRIPTION (COMMISCA)
☑ 0. SPILLS/LEAKING CONTAINERS/RUNO	
Leaking tanks caused the surf	ace water and groundwater contamination
!	
P. SEWER, STORM DRAIN PROBLEMS	
·	
Q. EROSION PROBLEMS	
displaying and the second of t	
R. INADEQUATE SECURITY	
en e	
weeks and a second of the seco	
and the second s	
S. INCOMPATIBLE WASTES	
with the second	
• • • decay	
AMERICAN STATE OF THE STATE OF	

ſ-		VIII. HAZARD DES	CRIPTION (continued)					
T. MIDNIGHT DUMPING					***************************************			
:								
			• .					
						•		
U. OTHER (apocity):								
		and the second s	and the state of t					
•						•		
	-	•	,					
					•			
					·			
					1.			
						•		
·								
	197	200111 4 21011 01056	TI V AFFECTED BY (7=				
	1.	POPULATION DIREC	TLY AFFECTED BY S					
A. LOCATION OF POPULATION	B. APPROX. NO.		C. APPROX. NO. OF PEOPLE AFFECTED WITHIN		D. APPROX. NO. OF BUILDINGS	E. DISTANCE TO SITE		
		OPLE AFFECTED	UNIT AREA		AFFECTED	(specify units)		
1 IN DESIDENTIAL ADDAG								
1.IN RESIDENTIAL AREAS		· ?	?		Aberjona Riv.	l Mile		
2 IN COMMERCIAL 2 OR INDUSTRIAL AREAS						,		
· _		N/A						
IN PUBLICLY 3° TRAVELLED AREAS								
	 -	N/A						
4. PUBLIC USE AREAS (parks, echools, etc.)		2	,		Aberiona Riv.	l Mile		
			D HYDROLOGICAL DAT	ГА	WET IONG KIN	T 13TTE		
A. DEPTH TO GROUNDWATER(apocity sait)		B. DIRECTION OF FLOW C. GROUNDWATER USE IN VICT			VICINITY			
approx. 10	SE		In		ndustrial			
D. POTENTIAL YIELD OF AQUIFER		E. DISTANCE TO DRI (specify unit of me	NKING WATER SUPPLY F		DIRECTION TO DRINKING WATER SUPPLY			
> 3 MGD ⁻		5 miles			S			
G. TYPE OF DRINKING WATER SUPP		1111 111	Wahiren					
1. HON-COMMUNITY X	2. COMMI >.15 C	JNITY (epocify town): DNNECTIONS	wopurn					
1	4. WELL							

Continued From	Page 8	•				
		X. WATER AND HYDROLO	GICAL DATA (c	ontinued)		
H. LIST ALL DRIN	KING WATER WE	LLS WITHIN A 1/4 MILE RADIUS OF	SITE		, , , , , , , , , , , , , , , , , , , 	
1. WELL	2. DEPTH (specify unit)	(proximity to	LOCATION population/buildir	nga)	NON-COM- MUNITY (mark 'X')	COMMUN- ITY (mark 'X')
None						
	<u> </u>					
			·			
'	<u> </u>				ļ	
I. RECEIVING WA	750		·· · · · · · · · · · · · · · · · · · ·		·	
1. NAME	IER	2. SEWERS	■ 3. STREAMS	RIVERS		
Aberjona R		4. LAKES/RESERVOIRS	5. OTHER(sp	pecify):	. 	
· ·		directly contaminated.	1.7-4.0m 12m126	ā	÷	
CIASS D DC		XI. SOIL AND VEG	· · · · · · · · · · · · · · · · · · ·			
LOCATION OF SI	TE IS IN:	444, 44				
_	FAULT ZONE	B. KARST ZONE		AR FLOOD PLAIN	D. WETLAND	
E. A REGUL	ATED FLOODWAY			RGE ZONE OR SOLE SOUR	CE AQUIFER	
is		XII, TYPE OF GEOLOGICAL of geological material observed and			narts.	
		of geological material observed and	a specify where i	lecessary, the component,	μαιτο.	
X A. CVERBUR	RDEN X	B. BEDROCK (specify below)	1	C. OTHER (apo	cify below)	
1. SAND		edrock near surface				
X 2. CLAY	1 1	t southern end of ite near landfill				
3. GRAVEL					·	
,		XIII. SOIL PER	RMEABILITY			
□ A. UNKNOWN	N TE (10 to .1 cm/sec	B. VERY HIGH (100,000 to		C. HIGH (1000 to 10 cm		· •c•)
G. RECHARGE AF	REA	COMMENTS:	7		· · · · · · · · · · · · · · · · · · ·	
H. DISCHARGE A		COMMENTAL				
_x 1. YES		COMMENTS:				
I. SLOPE	F SLOPE 2.	SPECIFY DIRECTION OF SLOPE, C	ONDITION OF SLO	OPE, ETC.		
?						
J. OTHER GEOLO	GICAL DATA					
•						
i						
						,

XIV. PERMIT INFORMATION									
List all applicable permits he	ld by the site and	provide the related inf	formation.						
A. PERMIT TYPE	2 12211112		D. DATE	E. EXPIRATION	F. IN COMPLIANCE (mark 'X')				
(e.g., RCRA, State, NPDES, etc.)	B. ISSUING AGENCY	C. PERMIT NUMBER	ISSUED (mo.,day,&yt.)	DATE (mo,day,&yr.)	1. YES	2. NO	3. UN-		
None		tanto y .							

		,		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
<u> </u>	YV PAST	REGULATORY OR EN	FORCEMENT ACT	IONS		<u> </u>	<u> </u>		
X NONE YES (summa	arize in this space)	REGULATOR! OR EN	TORCEMENT ACT	10113					
	nizo in imo spaco)		•						
						•			
				٠					
				•					
							·.		
		•							
, .									
	•			•					
. •			•						
. *									
. •									
				· ·	·				
				·					

PAGE 10 OF 10

EPA Form T2070-3 (10-79)

INSTRUCTION STORAGE FACILITIES SITE INSPECTION REPORT Answer and Explain (Supplemental Report) as Necessary. 1. STORAGE AREA HAS CONTINUOUS IMPERVIOUS BASE TYES X NO 2. STORAGE AREA HAS A CONFINEMENT STRUCTURE 3. EVIDENCE OF LEAKAGE/OVERFLOW (II "Yes", document where and how much runoff is overflowing or leaking from containment) X YES NO Small amount seeping into nearby drainage ditch. Monitoring well grossly contaminated 4. ESTIMATE TYPE AND NUMBER OF BARRELS/CONTAINERS 5. GLASS OR PLASTIC STORAGE CONTAINERS USED YES X NO 6. ESTIMATE NUMBER AND CAPACITY OF STORAGE TANKS 10 tanks, 6 in one group, 4 in another (5000 to 15000 gallon capacity) 7. NOTE LABELING ON CONTAINERS None 8. EVIDENCE OF LEAKAGE CORROSION OR BULGING OF BARRELS/CONTAINERS/STORAGE TANKS (11"Yes", document evidence. Describe location and extent of damage. Take PHOTOGRAPHS) YES X NO 9. DIRECT VENTING OF STORAGE TANKS YES DN E 10. CONTAINERS HOLDING INCOMPATIBLE SUBSTANCES (If "Yes", document evidence. Describe location and identity of hezardous waste. Take PHOTOGRAPHS.) YES NO 11. INCOMPATIBLE SUBSTANCES STORED IN CLOSE PROXIMITY (If "Yes", document evidence. Describe location and identity of hazardous waste. Take PHOTOGRAPHS.) YES X NO 12. ADEQUATE CONTAINER WASHING AND REUSE PRACTICES YES NO UNK

13. ADEQUATE PRACTICES FOR DISPOSAL OF EMPTY STORAGE CONTAINERS

N/A





Eames St., Wilmington, Massachusetts 01887

RECEIVED

JUL 2 6 19/3

MASS, DIVISION OF

WATER POLLUTION CCLITRON

July 18, 1973.

Mr. Thomas C. McMahon, Director The Commonwealth of Massachusetts Water Resources Commission Leverett Saltonstall Building Government Center 100 Cambridge Street Boston, Massachusetts 02202.

Dear Mr. McMahon:

The following is an item by item response to your letter of July 13, 1973.

- (1)The large volume of "industrial sludge" is pure calcium sulfate (gypsum) which had been lifted out of the secondary clarifier. This material has no odor and has not been eroded since being placed in its present posi-It became necessary to remove this material from the pond because overflow conditions were being reached as the pond had filled at a much faster rate than had been anticipated due to a lower rate of compaction as the solids level increased. I am sure that your Division is aware of the fact that Dana Perkins has been engaged to engineer a second secondary clarifying pond and also a sanitary landfill for the gypsum on our property adjacent to the Woburn City dump. The engineering work on both of these projects has been progressing and Mr. Tarbell of Public Health and Mr. Romano, Wilmington Health Officer, have made a preliminary inspection of the proposed landfill area and of the secondary clarifier. It was pointed out at this time that erosion had not taken place even with very heavy rains. The general plans as developed by our consultant, Dana Perkins, entail the use of two secondary clarifier ponds with one area cleaned each year by removal of the gypsum to the approved landfill area. These plans will be submitted to your Division for review as soon as preliminary approval is obtained from Public Health.
- (2) The PVC liner in the lagoon has not been broken in two places. only assume that this comment refers to several channels from the lagoon that were created by the pond overflowing for a short period before the calcium sulfate was removed.
- (3) The wells referred to were experimental borings, placed under pumping tests by the D. L. Maher Company of North Reading. We were assured by Mr. Maher that he had the right to conduct flow tests on these wells without obtaining permits. This flow was discontinued on February 5, 1973 and will not be restarted.
- The oil drums that receive the flow from the skimmer have been removed, the area cleaned and tight housekeeping will be maintained in the future.

cable: NAPOL telephone: (617) 933-4240



page 2

The oil seepage which was directed to our attention by your inspectors was at the railroad ditch level about 10 - 15 feet below grade and behind our chemical storage tank farm. All tanks and lines were examined and found to be free from leakage. The soil behind the tankfarm at grade level is sandy and clean with no indications of chemical runoff. Our water pollution consultants from the Badger Corporation examined this site and have theorized that the seepage could be due to natural occuring hydrocarbons being leached from the soil at the extremely high water table that was experienced in May of this year.

We have recently examined the railroad ditch under the prevaling conditions of a much lower water table and there are now only very slight traces of oil films in the ditch. I am sure that your Division is aware that this ditch is loaded with raw sewerage emanating from above our plant site and that the bottom of the ditch exhibits concentrations of black sludge which appears to be raw sewerage derived.

At the present time, we are cooperating very closely with the Town of Wilmington, the MDC, and Public Health to eliminate all of our problem areas through approved long-term solutions. The Badger Corporation are consulting with us on the mechanics of the treatment plant with particular concentration in the area of finding more efficient sump pumps to handle our effluent streams. We have attempted to cooperate fully with your Division as evidenced by our conducting engineering personnel from other companies through our facility at Mr. Bonne's request and offering our engineering designs free of charge. However, on the inspection level, we feel that cooperation has been less than desirable. During the last inspection, your people refused my invitation to enter the office building and discuss with me their findings. They indicated to the plant people that they were "too busy" to do this. On another occasion one of your inspectors drove an automobile directly into our plant and through several hazardous operating areas to the treatment plant. sure that you are aware under the OSHA regulations that we are responsible for the safety of all persons who enter our plant areas and that all visitors must be equipped with the proper safety equipment at the front office.

The key personnel in this Division are ready to discuss our entire program and the individual points raised in your letter of July 13 at any time convenient to your personnel.

Very truly yours,

NATIONAL POLYCHEMICALS
A Division of Stepan Chemical Company

Chales P. Riley Ir.

General Manager

CPR/jlp *

